


## Appendix A


### Site Reconnaissance Photographs

## Photograph 1



**View looking west to southwest at northeast corner of Impoundment D.  
Photograph taken from the northwest crest of Impoundment BC.**


## Photograph 2



**Photographs 2 through 5 present panoramic view of Impoundment D's northeast slope, viewed from northwest to southeast.**




### Photograph 3




**Photographs 2 through 5 present panoramic view of Impoundment D's northeast slope, viewed from northwest to southeast.**

**Photograph 4**



**Photographs 2 through 5 present panoramic view of Impoundment D's northeast slope, viewed from northwest to southeast.**


**Photograph 5**



**Photographs 2 through 5 present panoramic view of Impoundment D's northeast slope, viewed from northwest to southeast.**



**Photograph 6**



**Closer view of Impoundment D northeast slope showing erosion features along lower bench face.**

## Photograph 7



Erosion repairs to lower slope near southwest corner of Impoundment AB/BC using crushed furnace slag.



**Photograph 8**



**Erosion repairs to lower slope near southwest corner of Impoundment AB/BC using crushed furnace slag.**



**Photograph 9**



**Closer image of crushed furnace slag used for erosion repairs to lower bench near southwest corner of Impoundment AB.**


**Photograph 10**



**On-going erosion repairs to lower southwest facing slope of Impoundment AB using furnace slag. Area is near dividing berm between AB and BC impoundments.**




**Photograph 11**



**Severe erosion along crest of lower southwest facing slope of Impoundment AB. Furnace slag appears to be randomly placed for erosion protection.**


## Photograph 12



Photographs 12 through 17 illustrate panoramic view of southwest (this photo) side and corner of Impoundment AB looking from south to north.




### Photograph 13



Photographs 12 through 17 illustrate panoramic view of southwest (this photo) side of Impoundments AB/BC looking from south to north.




## Photograph 14




Photographs 12 through 17 illustrate panoramic view of southwest (this photo) side of Impoundment BC looking from south to north.

## Photograph 15



Photographs 12 through 17 illustrate panoramic view of southwest (this photo) side of Impoundment BC looking from south to north.


## Photograph 16



Photographs 12 through 17 illustrate panoramic view of southwest (this photo) side of Impoundment BC looking from south to north.




## Photograph 17



**Photographs 12 through 17 illustrate panoramic view of southwest (this photo) side of Impoundment BC looking from south to north.**

## Photograph 18



**Erosion repair along southwest of Impoundment AB/BC.**



## Photograph 19



**Southwest corner of Impoundment AB/BC near the North Emergency Tailings Pond.**



**Photograph 20**



Photographs 20 through 23 show panoramic southeast to northwest view of Gila River at toe of lower berm near Impoundment AB/BC.

## Photograph 21



Photographs 20 through 23 show panoramic southeast to northwest view of Gila River at toe of lower berm near Impoundment AB/BC.




**Photograph 22**



Photographs 20 through 23 show panoramic southeast to northwest view of Gila River at toe of lower berm near Impoundment AB/BC.

**Photograph 23**



Photographs 20 through 23 show panoramic southeast to northwest view of Gila River at toe of lower berm near Impoundment AB/BC.



**Photograph 24**



View near southwest corner of North Emergency Tailings Pond and Gila River. Railway trestle in background. Randomly placed riprap boulders in foreground along pond berm.